

Figure 1

Compressive strength





Figure 2

## Foam Shear Strength Test Method

Toray Plastics, (America)



### Toray Test Method

- (1) Adhere both sides of foam to Plywood board.
- (2) In an Instron Model 5565 instrument, pull one board at 100m/min.
- (3) Measure load at breaking point. This is foam shear strength.

5

Figure 3

Compressive strength

